



CITY OF ROTORUA

Street Damage Claim

VAL/No: 6993/017/02 Pt

I, the undersigned, certify that PRIOR TO ANY excavation, earthworks, the depositing of materials, or any other building operations in respect of the below-mentioned site, damage to Council property exists to the following extent.

EXTENT OF DAMAGE

LOT: 121 DPS: 33786 LOCATION: 3 Pohutukawa Dr

NIL

SIGNED:

DATE:

26/2/86

CHECKED:

DATE: